Technical Service Bulletins Savina, Overview:

Savina

#	Meaning, short description	Date
7	Replacement of some internal flow sensors, alarm "Flow measurement failure !!!"	03.02
6	Use and care of internal batteries	03.02
5	New software version 1.12 and new Operating Instructions	03.02
4	Improvement of EMC and other modifications	03.02
3	Improvement of EMC	2.01
2	New software version 1.11	07.01